

WINTER POLISHING PROCEDURES

In winter, there may be differences with the polishing procedure due to seasonal changes such as cooler floor temperatures and the addition of melting salts which can migrate indoors. With regards to the floor temperature, this could make it more difficult to rinse the floor properly which could leave films and/or residues behind.

For the solution to this, we recommend rinsing with hot water and buffing with a white pad. This should solve the residue issue entirely. In fact, we recommend it be done routinely any time of the year as it will also help with swirls and light over-etching issues as well.

Also, please make sure that buckets are kept well mixed, especially during periods of freeze/thaw. Even though there are no performance issues due to freeze/thaw, if the product becomes overly separated, inconsistencies could develop.



Regarding the salt migration issue, we recommend making sure the floor is well cleaned prior to polishing. Use of hot water is advised here too, to remove any salts prior to the polishing procedure. This will also raise the floor temperature helping with the polishing procedure.

